

Request that AD be ammended to correct the part number of applicable LPT stage 6 disks from P/N 6089T89P01 to P/N 6078T89P01 stated in AD summary and applicability (refer to GE ASB 72-A0173). Request to include original issue and previous revisions of GE Aircraft Engines, ASB No. CF34-AL S/B 72-A0173, for AD compliance of initial inspection or replacement and terminating action of applicable LPT stage 5 and 6 disks listed in figure 3.Independence Air (formally Atlantic Coast Airlines) had engines repaired (LPT disks either replaced or inspected)under the previous revisions of GE ASB No. 72-A0173.