

The proposed AD does not specify either the part numbers determined to be faulty or the part numbers mandated to be installed. Rather than blindly following the manufacturer's service bulletin, the FAA should cite the defective part numbers and suggest the alternative Bruce Industries product. There may be other acceptable PMA alternatives that can be used instead of the ones set forth in the AD, but without knowing the part numbers such a determination is difficult if not impossible.