118215

DEPT OF TRANSPORTATION
00 DEC 12 AM 11:17

NHTSA-00-8296-3

Mr. Glenn Fulmer
11505 Crows Nest Rd
Clarksville, MD 21029-1601

Senator Barbara Mukulski.

Relative to bad tires and tire safety I have a suggestion ALL OF THE KEY IDENTIFICATION information should be on the outside of the Tire. not on the inside, where it is hard to see without removing the tire or putting it on a lift.

I hope you can get this changed.

Sincerely

Glenn E. Fulmer