

Corrections

Federal Register

Vol. 64, No. 161

Friday, August 20, 1999

Tuesday, August 10, 1999, make the following corrections:

1. On page 43573, in the first column, in the 12th line, "§ 25.735(e9)" should read "§ 25.735(e)".
2. On the same page, in the same column, in the 20th line from the bottom, "satisfactory" should read "satisfactorily".
3. On the same page, in the third column, in the first full paragraph, in the 14th line from the end, remove "ensures the paragraph.""
4. On page 43574, in the second column, in the 17th line, after "services." remove "for" and add "five".

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. FAA-1999-6063; Notice No. 99-16] — 3

RIN 2120-AG80

**Revision of Braking Systems
Airworthiness Standards To
Harmonize With European
Airworthiness Standards for Transport
Category Airplanes**

Correction

In proposed rule document 99-205 18 beginning on page 43570 in the issue of

§ 25.731 [Corrected]

5. On page 43577, in the third column, in § 25.731 (e), in the third line, "§ 24.735" should read "§ 25.735".

§ 25.735 [Corrected]

6. On page 43578, in the first column, in § 25.735(e)(1), in the first line, "satisfactory" should read "satisfactorily".

[FR Doc. C9-20518 Filed 8-19-99; 8:45 am]

BILLING CODE 1505-01-0