

Pratt & Whitney Component Overhaul Singapore Pte. Ltd.

18 Loyang Crescent • Singapore 508982  
Tampines Central P.O. Box 0196 • Singapore 915207  
Telephone : (65) 545-4866 . Fax : (65) 542-7583  
Telex : RS 24565 PWCOS . Sita : SINIBCR



**Pratt & Whitney**  
A United Technologies Company

6253g

ORIGINAL

23<sup>rd</sup> August 1999

United States Department of  
Transportation Dockets  
400 Seventh Street, S.W.  
Room Plaza 401  
Washington, D.C. 20590

**RE:** Docket No FAA-1999-5836 - 49  
Notice No. 99-09

Dear Sir/Madam,

1. Enclosed, please find the letter "Requesting for **Ext:nsion** of Time for Comments" which are in duplicates.
2. Also enclosed, a copy of "Receipt Request" for acknowledgement of documents.
3. Thank you.

Sincerely

William Lee  
QA Engineer

99 SEP - 11:00  
PT OF THE  
DOCKET  
101  
101

encl.

Pratt & Whitney Component Overhaul Singapore Pte. Ltd.

18 Loyang Crescent . Singapore 508982  
Tampines Central P.O. Box 0196 . Singapore 915207  
Telephone : (65) 545-4866 . Fax : (65) 542-7583  
Telex : RS 24565 PWCOS • Sita : SINIBCR



23<sup>rd</sup> August 1999

United States Department of  
Transportation Dockets  
400 Seventh Street, S.W.  
Room Plaza 401  
Washington, D.C. 20590

RE: Docket No FAA-1999-5836  
Notice No. 99-09

Please consider this a Request for Extension of Time for Comments to the above referenced Docket under 14 C.F.R. §11.29(c).

Pratt & Whitney Component Overhaul Singapore Pte Ltd, Air Agency Certificate Number **POWY963N** is involved in the maintenance, and preventive maintenance of civil aviation products, components and parts and is currently certificated under 14 C.F.R. Part 145.

Upon review of the proposed NPRM, we **find** it too complex and detailed to submit a reasoned response within the time allotted. The proposed changes, including those related to monitoring of suppliers, training, tooling and many other factors will require in depth analysis to fully ascertain the impact upon our business and to respond in a complete and detailed manner. The proposed changes in the requirements for a Repair Station Manual and changes in the Repair Station Rating and Capability List requirements will require additional and continuing administrative burden upon our business.

In order to provide a proper response, each proposed change will need to be analyzed and comment made. We believe that good cause exists to extend the comment period to the maximum allowable. The FAA stated its own observation in the NPRM that this proposed rule had been under consideration since 1975, yet only 120 days were given for response. Considering the financial and compliance impacts upon our business that are contained in the NPRM, we respectfully request the FAA extend its Comment Period, at a minimum, to December 31, 1999.

Sincerely,



Richard Brawn  
Acting General Manager

Pratt & Whitney Component Overhaul Singapore Pte. Ltd.

18 Loyang Crescent • Singapore 508982  
Tampines Central P.O. Box 0196 • Singapore 915207  
Telephone : (65) 545-4866 • Fax : (65) 542-7583  
Telex : RS 24565 PWCOS • Sita : SINIBCR



**RECEIPT REQUEST**

Date: 23<sup>rd</sup> August 1999

Ref: Docket No. FAA-19994836  
Notice No. 99-09

No. of Copy: **2**

Company: Pratt & Whitney Component Overhaul Singapore Pte Ltd

Address: 18, Loyang Crescent  
Singapore 508982

Tel: **(65) 545-4866**

Fax: **(65) 542-7583**

Department: Quality Assurance

I acknowledge receipt of the documents sent under cover of the above letter reference.

Signature: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_