

As a Commercial Pilot and Air Traffic Control degree recipient, I believe that this Proposed Rule is one that can be implemented on certain occasions. It is obvious that the ATC equipment needs to be greatly updated, and that all aircraft operating at FL290 and above must be equipped with some sort of Collision Avoidance equipment. It was made all too apparent a couple weeks ago that RVSM can be dangerous, by the accident that occurred over Germany.