

AD2000-20-04 is not listed as an applicable AD to the MD-90 aircraft on the FAA web. After reviewing the AD, found it to be applicable. How can we trust the FAA website if it is not accurate.