

304288

[4910-13-U]

DEPARTMENT OF TRANSPORTATION (DOT)

Federal Aviation Administration

14 CFR Part 39

19496-2

[Docket No. FAA-2004-+++++; Directorate Identifier 2003-NM-181-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-215-6B11 (CL215T Variant) and CL-215-6B11 (CL415 Variant) Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier Model CL-215-6B11 (CL215T variant) and CL-215-6B11 (CL415 variant) series airplanes. This proposed AD would require replacing the mounting pad studs of the auxiliary feather pump with new, longer studs, and installing a pressure relief valve. This proposed AD is prompted by a few incidents of external oil leaks from the pump of the power control unit due to a malfunction of the pressure regulating valve. We are proposing this AD to prevent fracturing of the pump body, which could result in loss of engine oil, and consequent inability to maintain engine oil pressure and to feather the propeller.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

CONCURRENCES
ROUTING SYMBOL ANE-171
INITIALS/SIGNATURE R. Fiesel
DATE 7-7
ROUTING SYMBOL -7
INITIALS/SIGNATURE DA
DATE 10-14
ROUTING SYMBOL -114
INITIALS/SIGNATURE SC
DATE 10-18
ROUTING SYMBOL -101
INITIALS/SIGNATURE KJH
DATE 10/21/04
ROUTING SYMBOL -100
INITIALS/SIGNATURE KJH
DATE 10/21/04
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE
ROUTING SYMBOL
INITIALS/SIGNATURE
DATE