

I believe that the Administrator should take another look at 14CFR91.185(c)(3). Most controllers say that a lost-comms aircraft should land as soon as possible, not hold until an ETA that is unknown to ATC. This regulation must be brought into the 21st century.