

Although the glare/flare problem is present with the newer head lamps in cars, it is more noticeable in "SUVs". And that is because the headlight assembly is higher off the ground than on a car. The headlight assembly should be positioned lower on a SUV to reduce the discomfort to drivers of oncoming cars.