

91.1049 mentions 3 flight crew members per aircraft so there would be properly rested crews. No mention of duty time limitations for technicians as it relates to rest and safety